

Troubleshooting: Rotor Surface Overheating

Problem

Rotor Surface Overheating



Likely Cause

- Heavy thermal loads caused by sticking caliper piston
- Heavy thermal loads caused by sticking caliper slide pin
- Rotor surface deformation caused by heavy thermal loads

Solutions

- Replace the rotor
- Check for piston and slide pin sticking