

## Troubleshooting: Protruding Edge on Brake Rotor Surface

### Problem

Protruding edge on brake rotor surface



### Likely Cause

- Brake rotor shims are not installed
- Brake pad backing plate got in contact with rotor surface due to pad wear
- Rotor is worn out

### Solutions

- Check if brake rotor shims are installed
- Check the pad wear
- Check the rotor wear
- Replace the rotor