

AISIN

APPLICATION CORRECTION

DIFFERENTIAL ACTUATORS

Part Number Corrections


Please note that the e-catalog applications and OE reference numbers for the two part numbers below were originally reversed when they were announced. The CORRECT information is below. They have been corrected in the AISIN e-catalog to reflect what is shown below. The correction in the e-catalog was made on October 12, 2021 and the data will be sent to e-catalog providers at the end of the month. The data contained in OptiCat was corrected on October 14, 2021.

PART NUMBER: SAT-021

Make	Model	Year	Position
Toyota	4Runner	2001-2002	Front
	Sequoia	2001-2007	
	Tacoma	2001-2004	
	Tundra	2000-2006	

OEM REFERENCE:

41400-34010
41400-34011
41400-34012
41400-34013




PART NUMBER: SAT-020

Make	Model	Year	Position
Toyota	4Runner	2010-2020	Rear
	FJ Cruiser	2010-2014	

OEM REFERENCE:

41450-35040
41450-35041



For additional details and application information, please review the data provided by AISIN, or your catalog provider, or visit us on our website: www.aisinaftermarket.com
Contact your AISIN representative for additional information.

Distributed by